Sheet No.: BH 1.200.04 RevA

Date: October 2010

Standard paint specification Hempel Paint – Bettis BHH Products

Surface preparation: :



Oil and grease etc. to be removed by emulsion cleaning. Entire area to be (high pressure) fresh water cleaned in order to remove salts and other contaminants. When the surface is dry: Abrasive blasting to minimum Sa 2½ according to ISO 8501-1:1988.

The specified high film thickness can best be obtained by airless spray application. If another application method is used more applications are necessary to achieve the specified dry film thickness (200 micron wet / 125 micron dry.) Stripe coating with brush before or after spray application of each coat is to be carried out on areas difficult to cover properly by spray as eg edges, corners, flanges, cutouts, handwelds and other rough surfaces. The paint film dries to touch in four hours but must be fully cured (7 days/20°C) before the actuators can be taken into use.

Consult the separate APPLICATION INSTRUCTIONS for HEMPADUR 45141/45143.

Environment: Immersion.

Note: Not Certified dimensional drawings. Such drawings are available on request. Contact factory with correct model designation and serial number. Important: Due to Emerson's continuing commitment to engineered product advancement, data presented herin is subject to change.

The contents of the publication are presented for information purposes only, and while effort has been made to ensure their accuracy, they are not to be construed as warranties or guarantees, expresses or implied, regarding the products or services described herein or their use or applicability. All sales are governed by our terms and conditions, which are available on request.

We reserve the right to modify or improve the designs or specifications of our products at any time without notice.



