Subject: 820 v1.21 Firmware Service Bulletin

Overview

This documents the release of new firmware for 820. The version of this firmware is 1.21.

Products Affected

820

NAMUR NE 53 Rating

This release is rated at NAMUR NE 53 Level 3.

Products Affected

None

Resolution

None

Additional Features

The Drive Target can be modified and saved.



Micro Motion[®] Service Bulletin

MMI-SB-186, Rev A August 2019

Contact Information

Product information is available on the internet at: www.emerson.com.

Customer Service Phone Numbers:

Micro Motion USA	1-800-522-6277
Micro Motion Europe	31 (0) 318 495 555
Micro Motion Asia	65 6777-8211
Micro Motion UK	44 0870 240 1978
Micro Motion Japan	81 3 5769-6803

At Micro Motion we strive to stay on the leading edge of Coriolis technology. Upgrading to our latest MVD technology can pay for itself in a very short time period by improving your process measurement, improving diagnostic coverage, and improving the bottom line results of your process.

Thank you for your continued support.

© 2019 Micro Motion, Inc. All rights reserved.

ELITE, ProLink, and the Micro Motion logo are registered trademarks, and MVD and MVD Direct Connect are trademarks of Micro Motion, Inc., Boulder, Colorado. The Emerson logo is a trademark of Emerson Electric Co. All other trademarks are property of their respective owners.

Micro Motion supplies this publication for informational purposes only. While every effort has been made to ensure accuracy, this publication is not intended to make performance claims or process recommendations. Micro Motion does not warrant, guarantee, or assume any legal liability for the accuracy, completeness, timeliness, reliability, or usefulness of any information, product, or process described herein. For actual product information and recommendations, please contact your local Micro Motion representative.

